

High Performance Masking Tape Q1<sup>®</sup> High Performance Masking Tape has been specifically designed for most critical jobs in the automotive aftermarket and can withstand high temperatures of up to 110°C (230°F) for as long as 30 minutes. It is also UV resistant up to three days, making it ideal for projects where UV resistance is required.

Manufactured using crepe paper, it conforms well to curved and irregular surfaces and, thanks to a specific water resistance backing treatment, offers superb resistance to moisture, water and solvent based paints, as well as withstanding the process of wet sanding.



Features	<ul> <li>High conformability to curved and irregular surfaces</li> <li>Withstands temperature up to 110°C / 230°F (30 min.)</li> <li>Thin yellow translucent backing for high visibility during masking operations</li> <li>Special water resistance treatment for water-based paints and wet sanding applications</li> <li>Three days UV resistance</li> </ul>
Benefits	<ul> <li>The high-quality rubber-based adhesive formula provides a class-leading secure bond on multiple surfaces</li> <li>Compatible with waterborne and solvent-based coatings</li> <li>Better bonding to itself for improved painting process performance.</li> <li>Low-profile backing leaves smooth and sharp paint edges</li> <li>Translucent green colour for a better masking area visibility.</li> </ul>

Available Colour	Green				
Temperature Resistance	30 min.	60 min.			
	230°F / 110° C.	194°F / 90°			
Product Reference	Part#	Size		Pcs/ Case	
	HPT148	48mm X 50 / 55m		20 roll/ case	
	HPT136	36mm X 50 / 55m		24 roll/ case	
	HPT130	30mm X 50 / 55m		32 roll/ case	
	HPT124	24mm X 50 / 55m 18mm X 50 / 55m		36 roll/ case	
	HPT118			48 roll/ case	
Technical Data Sheet					
	Characteristics	Metric	Imperial Units	Test method	
	Total Weight	100 g/m2	100 g/m2	ISO 536	
	Total Thickness	130 µm	5.1 mils	Internal Method	
	MD tensile strength	42 N/cm	24 Lbs/in	AFERA 5004/PSTC 131	
	MD elongation at break	8%	8%	AFERA 5004/PSTC 131	
	Adhesion to steel plate	2.3 N/cm	21.0 oz/in	AFERA 5001/PSTC 101	



**Additional Information** 

## Storage & Handling

Q1<sup>®</sup> Premium Masking Solutions must be stored in a dry location, protected from direct sunlight exposure and from freezing. Storage temperatures should be as close as possible to room temperature; suggested storage temperature should range from 59°F / 15°C to 77°F / 25°C with max. relative humidity of 50%. Do not store tapes and related products in the paint booth during bake cycles.

Make sure the surface you wish to place the tape on is cleaned, dried and free from oil and dust. It is suggested not to apply the tape with temperatures lower than 50°F / 10°C. With a storage temperature lower than 50°F / 10°C, it is always suggested temperature reconditioning of the tape at room temperature (79°F / 15°C - 59°F / 25°C) before its use. We always recommend testing material in relation to the required applications.

## Shelf life from date of manufacture

No yellowing and < 10% loss in performance at 73.4°F / 23 °C, 50"% humidity is considered 12 months Q1<sup>®</sup> Premium Masking Solutions does not take responsibility for the defective material if is not stored and used in accordance with the conditions listed above.

## **Technical Information Disclaimer**

The technical information, suggestions and other statements contained in this documents have been compiled for your guidance and usage. Information is based on experience and tests that Q1<sup>®</sup> Premium Masking Solutions believe are reliable. The accuracy or completeness of such information is not guaranteed. Q1<sup>®</sup> Premium Masking Solutions has no control about conditions in which products are used, stores or handles. The above information doesn't constitute a warranty.

## **Product Use**

Q1<sup>®</sup> would advise that there are many factors beyond Q1<sup>®'</sup> control but within the users knowledge that can affect the use and performance of Q1<sup>®</sup> products. Q1<sup>®</sup> remind the user of the products to make sure that its range is used as per the instructions printed above. It is the users sole responsibility to determine that all preparation has been correctly carried out and that the working conditions are as per Q1<sup>®</sup> literature.

Via G. Terzi di S. Agata, 23 24030 Brembate di Sopra (BG) Italy

www.q1tapes.com contact@q1tapes.com

f in 🖸 D